From:

"Hardy, Russell" < Russell Hardy@consolenergy.com>

To:

"Hardy, Russell" < RussellHardy@consolenergy.com >, < pamgrubaughlittig@uta...

Date:

10/4/2007 11:26 AM

Subject: Attachments: Emery Subsidence Report Emery Subsidence 9-17-07.pdf

CC:

<karlhouskeeper@utah.gov>, <waynewestern@utah.gov>, <SteveChristensen@ut...</pre>

Please find attached the subsidence report for August.

Steve - September's report will be out after October 15th. Per Chapter 5 page 37 Consol committed to providing the subsidence report within a month of completing the data collection.

Russell Hardy CONSOL ENERGY Phone: (435) 286-3513 Fax: (435) 286-3516

email: russellhardy@consolenergy.com

Inco ggs

Consolidation Coal Emery Mine Subsidence Report for August 2007

8-23-07 Panel 14 West – Same as the previous inspection, old cracks seem to be filling in. New cracks are still forming where we are mining. A couple of the new cracks are noted to be about 1 inch wide. Pictures were taken (see below). PB



- 8-30-07 Panel 14 West Same as before new cracks are still forming where we are mining. Some of the old cracks have filled in enough to where they can't be found. PB
- 9-7-07 Panel 14 West Still seems to be acting the same. New cracks are forming over where we are mining. The cracks are roughly $\frac{1}{2}$ " 1" wide. PB
- 9-14-07 Nothing new over Panel 14 West. Cody Ware came and surveyed the subsidence over Panel 14 West. PB

Below is a map with the locations of the subsidence lines for the attached spreadsheet. Additionally, below is a summary of the flow data from SP-10 collected by Karla Knoop, from JBR Environmental.

Consol Emery Mine
Panel 14th West
Bryant No. 1
Flow Measurements made at dam
breach
Measurements taken by Karla Knoop

Date	Flow (gpm)
6/13/2007	77
7/24/2007	52
8/28/2007	75













